						Injury	Risk			
Equipment	Asset / Liability	No	Location	Details of Equipment	<u>Risk</u>	Detail	Level	Comments		
Item	Notice Board	1	Maypole Green	Wood structure and glass	Injury	1	Low	Satisfactory		
Item	Notice Board	1	Co op Station road	Wood structure and glass	Injury	1	Low	Satisfactory	Corrected address	
Item	Notice Board	1	Jubilee Cross	Wood structure and glass	Injury	1	Low	Satisfactory		
Item	Notice Board	1	Opposite co-op	Wood structure and cork	Injury	1	Low	Satisfactory		
Item	Notice Board	1	Opposite school	Wood structure and cork	Injury	1	Low	Satisfactory		
Items	Play Equipment	1	Churchill Green	For childeren under 8years old	Injury	2	Medium	Satisfactory		
Item	Playground/Area	1	Churchill Green	Flat ground	Injury	1	Low	Satisfactory		
Item	Playground Fence	1	Churchill Green	Perimeter Fence	Injury	1	Low	Good		
Item	Benches	2	Playground	Seating	Injury	1	Low	Satisfactory		
Item	Bench	1	Bartons Gound	Seating	Injury	1	Low	Fair	Seat board is loose	e
Item	Bench	1	Trafalger Green	Seating	Injury	1	Low	Satisfactory		
Item	Bench	1	Maggs Bridge	Seating	Injury	1	Low	Fair	some movement o	n base
Item	Bench	1	Field(New)	Seating	Injury	1	Low	Satisfactory	benefit from a pain	
Item	Bench	1	Field(New)	Seating	Injury	1	Low	Satisfactory	benefit from a pain	
Item	Bench	1	Field(New)	Seating	Injury	1	Low	Satisfactory	benefit from a pain	1
Item	Bench	1	Field(Metal)	Seating	Injury	1	Low	Satisfactory		
Item	Bench	1	Maypole Green	Seating	Injury	1	Low	Satisfactory		
Item	Bench	1	Churchill Close	Seating	Injury	1	Low	Satisfactory		
Item	Bench	1	Stocks Green	Seating	Injury	1	Low	Satisfactory		
Item	Bench	1	Churchill Green	Seating	Injury	1	Low	Satisfactory	benefit from a pain	1
Item	Bench	1	Churchill Green	Seating	Injury	1	Low	Satisfactory	benefit from a pain	1
Item	Bench	1	Churchill Green	Seating	Injury	1	Low	Satisfactory	benefit from a pain	1
Item	Bench	1	High street (Op P/O)	Seating	Injury	1	Low	Satisfactory		
Item	Bench(WI)	1	Mill moor	Seating	Injury	1	Low	Satisfactory		
Item	Maypole(inc base)	1	Maypole Green	Wood Pole+ Conrete base	See Note	3	High	Satisfactory		
Item	Metalwork	2	Maypole	Metalwork at 15m above FL	See Note	3	High	Satisfactory		
Item	Circular Bench	1	Mapole Green	Metal seating	Injury	1	Low	Satisfactory		
Item	Stone plaque	1	Mapole Green	Sign/Notice	Injury	1	Low	Good		
Item	Stocks Seat	1	Stocks Green	Wooden bench	Injury	2	Medium	Fair	Bench has movem	ent in it ar
Item	Stocks	1	Stocks Green	Wooden structure	Injury	1	Low	Satisfactory		
Item	Shelter (Base only)	1	Churchill Green	Concrete base	Injury	1	Low	Satisfactory		
Item	WW2 Pill Box	1	Whitemill Bridge	Concrete structure	Injury	2	Medium	Satisfactory		
Items	Dog Bins	1	Playground	Container on post	Health	1	Low	Satisfactory	Needs new lid	

	Bollards(Posts)			Container on post	Health	1	Low	Satisfactory		1
ltem V	Duilaius(FUSiS)		Greens various	Wooded Posts	Injury	2	Medium	Satisfactory		
ILGIII V	W/R Bonding Stone	1	Kings Street	Circular flat stone	Injury	2		Satisfactory	waste needs clear	ing away
Item V	War Memorial	1	High Street	Stone structure	Injury	2	Medium	Satisfactory		
ltem E	Book Box	1	Kings Street	Ex PO phone box	Injury	2	Medium	Satisfactory		
Items F	Flower Planters	3	Station Rd (op PO)	Containers	Injury	2	Medium		The left hand plan	ter had rot
Item F	Fence	1	The Pound	Fence	Injury	1	Low	Satisfactory		
Item S	Sundial	1	Chuchill Green	Flat ground mounted slabs	Injury	1	Low	Good		
SMPC Land										
Area m2										
24193 m2 (Churchill Green			Flat Ground	Injury	1	Low	Satisfactory		
880 m2 T	Timber/Stocks Green			Flat Ground	Injury	1	Low	Satisfactory		
710 m2	Maypole Green			Flat Ground	Injury	1	Low	Satisfactory		
Estd 30 m2 1	Trafalger Green			Flat Ground	Injury	1	Low	Satisfactory		
? J	Johnnies Ditch			Flat Ground	Injury	1	Low	Satisfactory		
? 1	The Pound			Flat Ground	Injury	1	Low	Satisfactory		
? N	Misc small parcels			Flat Ground	Injury	1	Low	Satisfactory		
? E	Bartons Ground			Flat Ground	Injury	1	Low	Satisfactory		
Misc. Items										
ר	Trophies		Details needed	????	????	1	Low			
	Storage Cabinets		Room	Metal Cabinets in Hall	Injury	1	Low			
F	Filing Cabinets		Room	Metal Cabinets in Hall	Injury	1	Low			
ד	Trees various		Within Parish	Large trees/branches	See Note	4	Very High			
Clerks Items										
L	Laptop		SMPC Clerk	Office equipment	Injury	1	Low			
F	Printer		SMPC Clerk	Office equipment	Injury	1	Low			
5	Software		SMPC Clerk	Office equipment	Injury	1	Low			
F	Printer Inks/ Paper		SMPC Clerk	Office equipment	Injury	1	Low			
F	Projector		SMPC Clerk	Office equipment	Injury	1	Low			
NOTES										
INJURY LEVEL1	Cuts/ STFs*		Slips/Trips/Falls*	Minor Injuries (SMPC advised)	Via P. Clerk					
	Level 1 +Hospital Visit		Play equipment	Inspect every month/12month	Reports					
INJURY LEVEL 3	Serious Injury		Maypole/Metalwork	Inspection every 12months	Plus report					
	As Level 3 / Death		All trees need RA	Inspection min 12 months	Plus report					
Any reported in	njury from SMPC equ	lipme	nt/property to be not	fied to PC/authority ASAP						

opposite co op no	needs replacing				
Church close no	All good order				

-	

	-									
and loose t	and loose top sleeper needs replacing									
-										
L										